

# Lab Report



Customer: Sample Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_

## Overview of Dust Bag(s)/Project Information

**1) Bag Size & Design:** This top loading filter bag was 148" long, had an approximately 8-3/4" wide flat (bag slit lengthwise during removal), a 2-3/4" separate cuff with a 9-3/4" long stainless steel mesh ground wire extension, a 5/8" wide 3-needle lap seam with stainless steel ground wire, and a standard disc bottom. The closest cell plate fit was 6.40" which was a loose fit. The media was an 18 oz/yd<sup>2</sup> unsupported, singed polyester felt.

**2) Bag Quantity:** 432 Bags (6 comp x 72 bags each)

**3) Process/Project ID:** TBD

**4) Problem (per customer):** Poor overall bag performance

**5) Service Life of Sample:** 4 months

**6) Desired Bag Life:** TBD


**7) Desired Emission Rate:** TBD

**8) Special Notes:** \_\_\_\_\_



Customer: \_\_\_\_\_ Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_

### Weight Analysis



### Permeability Analysis




FIGURE # 1



Customer: \_\_\_\_\_

Date: \_\_\_\_\_

Lab Report: \_\_\_\_\_

By: \_\_\_\_\_

### Strength Analysis ( Mullen Burst )







FIGURE # 2



Customer: \_\_\_\_\_ Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_



**Text:** Photograph # 1  
Clean Gas Side vs. Dust Side view of the top section. Up to a 1" thick layer of hardened aggressively attached dust was present on the Dust Side (exterior) surface. A 1/8" thick layer of hardened aggressively attached dust was present on the Clean Gas Side (interior) surface. This photograph is also representative of the middle section of the filter bag.




**Text:** Photograph # 2  
Clean Gas Side vs. Dust Side view of the bottom section. Up to an 1/8" thick layer of hardened aggressively attached dust was present on the Dust Side (exterior) surface. A 1/16" thick layer of hardened aggressively attached dust was present on the Clean Gas Side (interior) surface.







Customer: \_\_\_\_\_ Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_




**Text:** Photograph # 3  
Cross section view from the top of  
the bag.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_




**Text:** Photograph # 4  
Cross section view from the middle  
of the bag.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_




Customer: \_\_\_\_\_ Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_



**Text:** Photograph # 5  
Cross section view from the bottom  
of the bag.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Dust Penetration Scale



**Text:** Photograph # 6  
Cross section view from a clean,  
unused sample of 18 oz/yd<sup>2</sup>  
unsupported, singed polyester felt for  
comparison against the used felt  
shown in Photographs #3, #4 and #5.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_





Customer: \_\_\_\_\_ Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_

Dust Side



**Text:** Photograph # 7  
Dust Side view of the filter bag as  
received to the lab. The filter bag  
was slit lengthwise during removal.  
A heavy layer of aggressively  
attached dust was evident the entire  
length of the filter bag.

Dust Side



**Text:** Photograph # 8  
Dust Side view of the top portion of  
the bag illustrating thick, bark-like  
agglomerations adhered to the  
external bag surface.



Customer: \_\_\_\_\_ Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_



**Text:** Photograph # 9  
Clean Gas Side view showing a heavy layer of ubiquitous brown, red, and white dust coating the interior bag surface. This photograph is representative of the entire length of the filter bag on the interior side.





Customer: \_\_\_\_\_ Date: \_\_\_\_\_  
Lab Report: \_\_\_\_\_ By: \_\_\_\_\_

## Lab Analysis Summary

**Physical Damage:** There was no physical damage from the process present on this filter bag. The bag was split during removal.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Chemical Attack:** Possible due to a 45% loss in Mullen Burst strength.

**Hydrolytic Attack:** Possible due to a 45% loss in Mullen Burst strength.

**Dust Cake Formation:** A thick, bark-like layer of reddish-brown dust coated the entire outside of the bag, with a thinner layer of dust coating the interior side.

**Dust Penetration:** See Dust Penetration Photographs.

**Additional Comments:** The permeability and Mullen Burst strength after air pulse cleaning were 12.29 cfm and 330 psi respectively. This represents an 18% loss in permeability (original specification of 15 cfm) and a 45% loss in Mullen Burst strength (original specification of 600 psi).

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_